

Sponge pad (ø4 ~ ø15)

S-ZP2 SERIES


How to order



S-ZP2- ① 06 ② S


① Pad Diameter (mm)		② Pad Material	
04	ø4	S	Sponge
06	ø6		
08	ø8		
10	ø10		
15	ø15		

For The Adsorption Of Workpieces With Bumps




Dimension


(mm)




S-ZP2-04S




S-ZP2-06S



S-ZP2-08S



S-ZP2-10S



S-ZP2-15S

How to order



S-ZP2- ① T ② 06 ③ S - ④ A5

① Vacuum Inlet Direction	
Symbol	Direction
T	Vertical

② Pad Diameter	
04	ø4
06	ø6
08	ø8
10	ø10
15	ø15

③ Pad form	
S	Sponge

④ Mounting						
Symbol	Thread Size	Applicable Pad Diameter (mm)				
		04	06	08	10	15
A3	M3x0.5 (Male thread)	●	-	-	-	-
A5	M5x0.8 (Male thread)	-	●	●	●	●
B3	M3x0.5 (Female thread)	●	-	-	-	-
B5	M5x0.8 (Female thread)	-	●	●	●	●

M3x0.5
M5x0.8
M3x0.5
M5x0.8


Model	Pad Model	Adapter Model
S-ZP2-T04S-A3	S-ZP2-04S	S-ZP2A-S01P
S-ZP2-T06S-A5	S-ZP2-06S	S-ZP2A-S02P
S-ZP2-T08S-A5	S-ZP2-08S	S-ZP2A-S03P
S-ZP2-T10S-A5	S-ZP2-10S	S-ZP2A-S04P
S-ZP2-T15S-A5	S-ZP2-15S	S-ZP2A-S05P
S-ZP2-T04S-B3	S-ZP2-04S	S-ZP2A-S11
S-ZP2-T06S-B5	S-ZP2-06S	S-ZP2A-S12
S-ZP2-T08S-B5	S-ZP2-08S	S-ZP2A-S13
S-ZP2-T10S-B5	S-ZP2-10S	S-ZP2A-S14
S-ZP2-T15S-B5	S-ZP2-15S	S-ZP2A-S15

Sponge pad ($\varnothing 4 \sim \varnothing 15$)


S-ZP2 SERIES

Dimension


(mm)




ZP2-T04S-A3




ZP2-T06S-A5




ZP2-T08S-A5




ZP2-T10S-A5




ZP2-T15S-A5




ZP2-T04S-B3




ZP2-T06S-B5



ZP2-T08S-B5



ZP2-T10S-B5



ZP2-T15S-B5